

Your feedback is important to us. Please rate our efforts related to the recent pavement surface treatment in your neighborhood.	Excellent	Good	Average	Needs work	Poor	Not applicable
Adequate notification of scheduled road work	✓					
Access to information about the work, schedules	✓					
Appropriate advance warning signs, work zone marked clearly	✓					
Feeling safe moving through work zone	✓					
Professional actions and appearance of road workers	✓					
Comments about this road work PAVEMENT COMPACTION MAY BE INSUFFICIENT AND SHOULD BE INSPECTED. WATER VALVE SERVICING HYDRANT AT 1717 SW WASHINGTON PAVED OVER, HAS NOT BEEN UNCOVERED.						
Road work location (road name) SW WASHINGTON DR.						

Your feedback is important to us. Please rate our efforts related to the recent pavement surface treatment in your neighborhood.	Excellent	Good	Average	Needs work	Poor	Not applicable
Adequate notification of scheduled road work	X					
Access to information about the work, schedules	X					
Appropriate advance warning signs, work zone marked clearly	X					
Feeling safe moving through work zone	X					
Professional actions and appearance of road workers.	X					
Comments about this road work You have the nicest most courteous employees! Thanks to all of them! The muller's 17641 SW Washington Cr.						
Road work location (road name) Washington Drive to Meadow Brook, Beaverton						

Your feedback is important to us. Please rate our efforts related to the recent pavement surface treatment in your neighborhood.	Excellent	Good	Average	Needs work	Poor	Not applicable
Adequate notification of scheduled road work	X					
Access to information about the work, schedules	X					
Appropriate advance warning signs, work zone marked clearly	X					
Feeling safe moving through work zone	X					
Professional actions and appearance of road workers	X					
Comments about this road work <i>Very well organized. Few delays. Workers were very pleasant, helpful &amp; courteous</i>						
Road work location (road name) <i>Old Scholls Ferry Rd</i>						

*Delightfully surprised how efficient & well organized they were.*

Your feedback is important to us. Please rate our efforts related to the recent pavement surface treatment in your neighborhood.	Excellent	Good	Average	Needs work	Poor	Not applicable
Adequate notification of scheduled road work	X					
Access to information about the work, schedules		X				
Appropriate advance warning signs, work zone marked clearly	X					
Feeling safe moving through work zone	X					
Professional actions and appearance of road workers	X					
Comments about this road work <i>Great Job!</i>						
Road work location (road name) <i>LAUREL LEAF LANE at Old Scholls Ferry Rd.</i>						

Your feedback is important to us. Please rate our efforts related to the recent pavement surface treatment in your neighborhood.	Excellent	Good	Average	Needs work	Poor	Not applicable
Adequate notification of scheduled road work						✓
Access to information about the work, schedules						✓
Appropriate advance warning signs, work zone marked clearly						✓
Feeling safe moving through work zone				✓		
Professional actions and appearance of road workers	✓					
Comments about this road work - APTS RESIDENTS ONLY REC'D 2 days notice from Mgr. NOT ENOUGH TIME TO RESCHEDULE DOCTOR APTS - WORK CAR POOLS, ETC - POOR NOTICE FROM PG&W						
Road work location (road name) SW. OLD SCHOLLS FERRY ROAD						