

Your feedback is important to us. Please rate our efforts related to the recent pavement surface treatment in your neighborhood.	Excellent	Good	Average	Needs work	Poor	Not applicable
Adequate notification of scheduled road work						
Access to information about the work, schedules						
Appropriate advance warning signs, work zone marked clearly						
Feeling safe moving through work zone						
Professional actions and appearance of road workers						
Comments about this road work they did a lousy job, some places it does't reach the curb. some places it looks like the street was scraped.						
Road work location (road name) S.W. 194th ave. in Aloha 11111						

Your feedback is important to us. Please rate our efforts related to the recent pavement surface treatment in your neighborhood.	Excellent	Good	Average	Needs work	Poor	Not applicable
Adequate notification of scheduled road work		X				
Access to information about the work, schedules		X				
Appropriate advance warning signs, work zone marked clearly		X				
Feeling safe moving through work zone						X
Professional actions and appearance of road workers						X
Comments about this road work (Didn't see)						
Road work location (road name) NW MALHUR AVE						

Your feedback is important to us. Please rate our efforts related to the recent pavement surface treatment in your neighborhood.	Excellent	Good	Average	Needs work	Poor	Not applicable
Adequate notification of scheduled road work		✓				
Access to information about the work, schedules		✓				
Appropriate advance warning signs, work zone marked clearly		✓				
Feeling safe moving through work zone		✓				
Professional actions and appearance of road workers		✓				
Comments about this road work I called regarding BSD Sp. Needs bus conflict. The Supervisor addressed my needs & concern.						
Road work location (road name) SW Winchester / Waverly Pl						

Work was completed prior to bus dropoff @ 3pm. Thank you